



# UH-60 ROTOR BLADE TIP CAP REPAIR & OVERHAUL



P/N: 70150-09207-041/-044  
NSN: 1560-01-447-9774



**INSPECTION                      \$325.00 EA.                      TAT = 5 DAYS**

Clean; Inspect Visually; Balance; Preserve & Package

**REPAIR                              \$1130.00 EA.                      TAT = 20 DAYS**

Clean; Pre-Repair Balance; Visually Inspect; Light Sand; Blend; Adhesive Patch; Paint; Post Repair Balance; Preserve & Package

**OVERHAUL                          \$1835.00 EA.                          TAT = 30 DAYS**

Clean; Pre-Repair Balance; Visually Inspect; Full Complete Sand; Wire Mesh Repair/Replacement; Adhesive/Cure/Vacuum Bag; Paint; Post Repair Balance; Preserve & Package

**WOMAN OWNED SMALL BUSINESS**

**BOEING GOLD SUPPLIER**

**US AIR FORCE & US ARMY PRIME CONTRACTOR**

**20 YEARS OF PROVIDING EXCELLENT  
REPAIR & OVERHAUL SERVICE**



**Contact Us for Pricing & Capability Questions:**

**PAS MRO, Inc.**  
**CAGE CODE: 3LSF6**

**1200 S. Maple Street, Bristow, OK 74010**

**[www.pasmro.com](http://www.pasmro.com)**

**FAA CERTIFICATE NO: 5POR020C**  
**EASA CERTIFICATE NO: EASA.145.6544**

**Ph: 918/771-4361**