




UH-60 STABILATOR LINEAR ACTUATOR REPAIR & OVERHAUL



P/N: 70400-06641-117
DL2155M20
NSN: 1680-01-261-2044

INSPECTION \$525.00 EA. TAT = 10 DAYS

Clean; Inspect Visually; Test; Findings Report

REPAIR \$3185.00 EA. TAT = 30 DAYS

Pre-Repair Shop Analysis; Disassembly; Clean; Component Inspection; Consumables Replacement; Minor Repair; Replacement of Unserviceable Components; Assembly; Test; Seal; Paint; Preserve & Package.


OVERHAUL \$4575.00 EA. TAT = 30 DAYS

Pre-Repair Shop Analysis; Disassembly; Clean; Component Inspection; Consumables Replacement; Repair; Replacement of All Mandatory Replacement Components; Assembly; Test; Seal; Paint; Preserve & Package.

WOMAN OWNED SMALL BUSINESS

BOEING GOLD SUPPLIER

US AIR FORCE & US ARMY PRIME CONTRACTOR



**20 YEARS OF PROVIDING EXCELLENT
REPAIR & OVERHAUL SERVICE**



Contact Us for Pricing & Capability Questions:

PAS MRO, Inc.
CAGE CODE: 3LSF6

FAA CERTIFICATE NO: 5POR020C
EASA CERTIFICATE NO: EASA.145.6544

1200 S Maple Street, Bristow, OK 74010

Ph: 918/771-4361

www.pasmro.com